#20150223-0815   Clause: 7.6.1.3   Page: 46   Line: -   Commenter: Marek Hajduczenia / Bright House Networks
Comment Status: Received   Category: -

In describing tunneling and VLAN modes for ONU and OLT tests, the the name of step 2 in each test case is too generic and should reflect the name and scope of the actual test case.

Page 46, change step 2 to read: "Step 2 ONU transport mode, upstream direction"

Page 48, change step 2 to read: "Step 2 ONU transport mode, downstream direction"

Page 52, change step 2 to read: "Step 2 ONU encapsulation mode, upstream direction"

Page 56, change step 2 to read: "Step 2 ONU encapsulation mode, downstream direction"

Page 61, change step 2 to read: "Step 2 ONU transport PB VLAN mode, upstream direction"

Page 64, change step 2 to read: "Step 2 ONU transport PB VLAN mode, downstream direction"

Page 67, change step 2 to read: "Step 2 ONU encapsulation PB VLAN mode, upstream direction"

Page 67, change step 2 to read: "Step 2 ONU encapsulation PB VLAN mode, downstream direction

Page 97, change step 2 to read: "Step 2 OLT transport and encapsulation modes, upstream direction"

Page 100, change step 2 to read: "Step 2 OLT transport and encapsulation modes, downstream direction"

Page 105, change step 2 to read: "Step 2 OLT transport and encapsulation PB VLAN modes, upstream direction"

Page 107, change step 2 to read: "Step 2 OLT transport and encapsulation PB VLAN modes, downstream direction"

Impact: None. The change is purely editorial

-

#20150223-0817   Clause: 8.4.2   Page: 99   Line: -   Commenter: Marek Hajduczenia / Bright House Networks
Comment Status: Received   Category: -

Title of test case AT-TTM1-02 is different than AT-TTM1-01, even though they are intended to be complimentary (one for upstream and another for downstream directions)

Change title of AT-TTM1-02 test case to "Test case for tunneling mode support, transport and encapsulation modes, downstream direction" - change needs to be applied to 8.4.2 heading only.

Impact: None. The change is purely editorial

-

#20150227-0938   Clause: 6.5.1   Page: 29   Line: -   Commenter: Lu Yang / RITT, CATR
Comment Status: Received   Category: -

In Table 33, the value of Match Value Length field can not be a fixed value

In the Table 33, change 0x03 to Varies

Impact: None

-

#20150228-0034   Clause: 6.5.1   Page: 29   Line: -   Commenter: Lu Yang / RITT, CATR
Comment Status: Received   Category: -

In Table 33, MSB Mask field should be set to 0x00.

change the value of MSB Mask field in Table 33 from 0x18 to 0x00.

Impact: None

-

#20150228-0038   Clause: 6.5.1   Page: 29   Line: -   Commenter: Lu Yang / RITT, CATR
Comment Status: Received   Category: -

In Table 33, Size of Match Value field should be varies.

change the Size of Match Value field in Table 33 from 3 to Varies.

Impact: None

-

#20150228-0056   Clause: 6.5.4   Page: 30   Line: -   Commenter: Lu Yang / RITT, CATR
Comment Status: Received   Category: -

In Table 36, Size of Field Code field should be 1. And Field Instance field is missing.

change the Size of Field Code field in Table 36 from 2 to 1. And insert a line to the bottom of Table 36, with Size = 1, Field = Field Instance, Value = 0x00.

Impact: None

-

#20150228-0103   Clause: 7.3.2.3   Page: 37   Line: -   Commenter: Lu Yang / RITT, CATR

Comment Status: Received   Category: -

In "Expected Result 4: During the period of one minute of execution of step 2.1", step 2.1 should be step 2.4
change step 2.1 in Expected Result 4 to step 2.4. Impact: None
-

#20150302-1919   Clause: 8.3.3.2   Page: 93   Line: -   Commenter: Glen Kramer / Broadcom

Comment Status: Received   Category: -

In step 3.3, the test procedure uses the primitive eOAMR_FTD(blockData, nextBlock). But no such primitive is defined.
Use the correct name eOAM_FTD(blockData, nextBlock) (no letter "R") Impact: None.
-

#20150316-1747   Clause: 2   Page: 4   Line: -   Commenter: Marek Hajduczenia / Bright House Networks

Comment Status: Received   Category: -

IEEE Std 802.1Qâ„¢-2011 has bee updated to 2014 version, incorporating a bunch of other versions and revisions.
Change "IEEE Std 802.1Qâ„¢-2011" in Clause 2 to "IEEE Std 802.1Qâ„¢-2014". Impact: None - it is just editorial update to the latest version of the standard
-

#20150227-2129   Clause: 6.5.3   Page: 29   Line: -   Commenter: Lu Yang / RITT, CATR

Comment Status: Received   Category: -

Insert result can not carry values. After insert a new field, a SET result is required to set the value of the new field. And the length of field code should be 1.
change Table 35 as proposed in rmtf_1502_lu_1.pdf Impact: None
-